

Irrigation Technical Inspection Report

Irrigation Controller			Point of Connection			Site Name: <i>Lower Store</i>		
Location: <i>Mail Area</i>			Location: <i>R. 1.1.1. 8590</i>			Location: <i>5.1.1</i>		
Type/Size			Size			Technician: <i>Carlos Rueda</i>		
Rain Gauge: Y <input checked="" type="checkbox"/> N <input checked="" type="checkbox"/>			Source: <input checked="" type="checkbox"/> Meter <input type="checkbox"/> Well <input type="checkbox"/> Pump			Date of Inspection: <i>1 - Sun 2017</i>		
Power On: <input checked="" type="checkbox"/> N						Inspection #: <i>1</i> of <i>5</i> in contract		
General Information			Backflow: <input checked="" type="checkbox"/> N			Inspection Start Time: <i>12:10</i>		
Valve Type			PRV: Y <input checked="" type="checkbox"/> N			Inspection End Time: <i>12:40</i>		
Adequate Coverage: <input checked="" type="checkbox"/> N			Master Valve: Y <input checked="" type="checkbox"/>			Set to Run: Odd Even Every Days		
						or Days of the Week: <i>S M T W T F S</i>		

		Repairs Proposed (P) or Completed (C)														Comments and Recommendations					
Controller	Plant Type	Pipes		Valves		Broken Heads			Adjustments												
Zone	Head Type (Rotor, Spray, Drip, etc.)	Turf	Shrub	Annual	Mainline Break	Lateral Line Break	Zone Not Responding	Valve Leaking	Zone Not Shutting Down	Turf Spray (4")	Shrub Spray (12")	Fixed Riser	Gear Driven Rotor	Impact Rotor	Cleaned/Replaced Nozzle		Adjust Spray Pattern	Straightened	Capped	Raised/Lowered	
15	1	S	/	/																	<i>A - 8. PM</i>
15	2	S	/	/																	<i>Mail Area</i>
15	3	S	/	/																	<i>9476-9474</i>
	4	UR																			<i>9480-9498 S.W.</i>
	5	NR																			
15	6	S	/	/																	<i>8691-8661</i>
15	7	S	/	/																	<i>8649-8631</i>
15	8	S	/	/																	<i>8607-8589</i>
15	9	S	/	/																	<i>8583-8529</i>
15	10	S	/	/																	<i>9380-9436</i>
15	11	S	/	/																	<i>Back Mail Area Road</i>
15	12	R	/	/																	<i>9499-8631</i>
15	13	R	/	/																	<i>8607-1.1.1.6</i>
15	14	R	/	/																	<i>8907-8589</i>
15	15	R	/	/																	<i>8583-952</i>
15	16	R	/	/																	
	17																				
	18																				
	19																				
	20																				
	21																				
	22																				
	23																				
	24																				

Comments

Irrigation Technical Inspection Report

Irrigation Controller			Point of Connection			Site Name: <i>Arroyo Grande</i>		
Location: <i>8725-8714</i>			Location: <i>R. 16th 8590</i>			Location:		
Type/Size: <i>R.D.</i>			Size:			Technician: <i>Chris Robert</i>		
Rain Gauge: <i>Y</i> <i>N</i>			Source: <i>Meter</i> <i>Well</i> <i>Pump</i>			Date of Inspection: <i>1 - Jun - 2017</i>		
Power On: <i>Y</i> <i>N</i>						Inspection #: <i>of</i> <i>in contract</i>		
General Information			Backflow: <i>Y</i> <i>N</i>			Inspection Start Time: <i>12:45</i>		
Valve Type:			PRV: <i>Y</i> <i>N</i>			Inspection End Time: <i>1:50</i>		
Adequate Coverage: <i>Y</i> <i>N</i>			Master Valve: <i>Y</i> <i>N</i>			Set to Run: <i>Odd</i> <i>Even</i> <i>Every</i> <i>Days</i>		
						or Days of the Week: <i>S M T W T F S</i>		

Controller		Plant Type			Repairs Proposed (P) or Completed (C)										Comments and Recommendations							
Zone	Head Type (Rotor, Spray, Drip, etc.)	Turf	Shrub	Annual	Mainline Break	Lateral Line Break	Zone Not Responding	Valve Leaking	Zone Not Shutting Down	Turf Spray (4")	Shrub Spray (12")	Fixed Riser	Gear Driven Rotor	Impact Rotor		Cleaned/Replaced Nozzle	Adjust Spray Pattern	Straightened	Capped	Raised/Lowered		
1		/	/																		8725-8726	
2		/	/																			8720-8702
3		/	/																			8846-8678
4		/	/																			8672-8654
5		/	/																			8648-8630
6		/	/																			8624-8606
7		/	/																			8590-8572
8	S.R.	/	/																			8566-8558
9	S	/	/																			8548-8530
10	R	/	/																			8524-8506
11	R	/	/																			Exit. + Back. - 8506
12	R	/	/																			Back. 8554 8672
13	R	/	/																			8684 - 8726
14	R	/	/																			8726 - 8725
15	R	/	/																			8714 - 8629
16	R.S	/	/																			8605
17	R	/	/																			8650 - 8668
18	S.R	/	/																			8674 - 8692
19	S.R	/	/																			8658
20		/	/																			8605 - 8623
21		/	/																			1 side 8623
22		/	/																			8629 - 8647
23		/	/																			8653 - 8671
24		/	/																			8677 - 8711
Comments		/	/																			

9-PM
A - M.W.F.
B - T.T.S

Irrigation Technical Inspection Report

Irrigation Controller			Point of Connection			Site Name: <i>Corona State</i>		
Location	<i>3464 827</i>		Location	<i>RS 8590</i>		Location:		
Type/Size	<i>RS</i>		Size			Technician: <i>Carl Reibert</i>		
Rain Gauge	Y	<input checked="" type="checkbox"/>	Source	<input checked="" type="checkbox"/> Meter	Well	Date of Inspection: <i>1 - Jun - 2017</i>		
Power On	<input checked="" type="checkbox"/>	N				Inspection #: of in contract		
General Information			Backflow	<input checked="" type="checkbox"/>	N	Inspection Start Time: <i>1:50</i>		
Valve Type			PRV	Y	<input checked="" type="checkbox"/>	Inspection End Time: <i>2:10</i>		
Adequate Coverage	<input checked="" type="checkbox"/>	N	Master Valve	Y	<input checked="" type="checkbox"/>	Set to Run: Odd Even Every Days		
						or Days of the Week: <i>S M T W T F S</i>		

Controller		Plant Type			Repairs Proposed (P) or Completed (C)											Comments and Recommendations						
Zone	Head Type (Rotor, Spray, Drip, etc.)	Turf	Shrub	Annual	Pipes		Valves			Broken Heads			Adjustments									
					Mainline Break	Lateral Line Break	Zone Not Responding	Valve Leaking	Zone Not Shutting Down	Turf Spray (4")	Shrub Spray (12")	Fixed Riser	Gear Driven Rotor	Impact Rotor	Cleaned/Replaced Nozzle	Adjust Spray Pattern	Straightened	Capped	Raised/Lowered			
1	<i>R</i>	<i>/</i>	<i>/</i>													<i>/</i>	<i>/</i>				<p><i>A) 12:30 AM M W F</i></p> <p><i>B) 12 AM T. 7. 5</i></p> <p><i>Mid. Field from JSD + Phoenix</i></p>	
2	<i>R</i>	<i>/</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>					
3																						
4																						
5																						
6																						
7																						
8																						
9																						
10																						
11																						
12																						
13																						
14																						
15																						
16																						
17																						
18																						
19																						
20																						
21																						
22																						
23																						
24																						

Comments

Irrigation Technical Inspection Report

Irrigation Controller			Point of Connection				Site Name: <i>Amey Stone</i>	
Location: <i>R. Side - 4007</i>			Location: <i>Back - 4007</i>				Location:	
Type/Size: <i>KB</i>			Size: <i>2 in</i>				Technician: <i>Patricia Rebert</i>	
Rain Gauge: <input checked="" type="checkbox"/> N			Source: <input checked="" type="checkbox"/> Meter <input type="checkbox"/> Well <input type="checkbox"/> Pump				Date of Inspection: <i>1 - Jun - 2017</i>	
Power On: <input checked="" type="checkbox"/> N							Inspection #: of in contract	
General Information			Backflow: <input checked="" type="checkbox"/> N				Inspection Start Time: <i>2:20</i>	
Valve Type			PRV: <input type="checkbox"/> Y <input checked="" type="checkbox"/> N				Inspection End Time: <i>3:30</i>	
Adequate Coverage: <input checked="" type="checkbox"/> N			Master Valve: <input type="checkbox"/> Y <input checked="" type="checkbox"/> N				Set to Run: Odd Even Every Days	
							or Days of the Week: <i>S M T W T F S</i>	

		Repairs Proposed (P) or Completed (C)															Comments and Recommendations				
Zone	Head Type (Rotor, Spray, Drip, etc.)	Plant Type			Pipes		Valves			Broken Heads			Adjustments								
		Turf	Shrub	Annual	Mainline Break	Lateral Line Break	Zone Not Responding	Valve Leaking	Zone Not Shutting Down	Turf Spray (4")	Shrub Spray (12")	Fixed Riser	Gear Driven Rotor	Impact Rotor	Cleaned/Replaced Nozzle	Adjust Spray Pattern	Straightened	Capped	Raised/Lowered		
1	<i>S</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>				<i>A.W. - P.M.</i>	
2	<i>S</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>				<i>B. 9. P.M. Flower</i>	
3	<i>S</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>					
4	<i>S</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>					
5	<i>S</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>				<i>S.W. + Panel.</i>	
6	<i>R</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>				<i>Back to 8601-8609</i>	
7	<i>R</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>				<i>11 8613-8627</i>	
8	<i>R</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>				<i>8631-8647</i>	
9	<i>R</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>				<i>8657-8665</i>	
10	<i>R</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>				<i>8669 to Panel</i>	
11	<i>R</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>				<i>S.W. Bu Panel</i>	
12	<i>R</i>	<i>/</i>	<i>/</i>												<i>/</i>	<i>/</i>				<i>Back Panel + flower</i>	
13																					
14																					
15																					
16																					
17																					
18																					
19																					
20																					
21																					
22																					
23																					
24																					

Comments
