

# Irrigation Technical Inspection Report

Irrigation Controller			Point of Connection			Site Name: <i>Cosner Stone</i>		
Location	<i>On Island</i>		Location			Location: <i>Argyle Forest</i>		
Type/Size	<i>Hunter</i>		Size			Technician: <i>Patricia</i>		
Rain Gauge	<input checked="" type="checkbox"/>	N	Source	<input checked="" type="checkbox"/> Meter	Well	Pump	Date of Inspection: <i>2-5-18</i>	
Power On	<input checked="" type="checkbox"/>	N				Inspection #: of in contract		
General Information			Backflow	<input checked="" type="checkbox"/>		N	Inspection Start Time: <i>7:00</i>	
Valve Type			PRV	Y		<input checked="" type="checkbox"/> N	Inspection End Time: <i>9:00</i>	
Adequate Coverage	<input checked="" type="checkbox"/>	N	Master Valve	Y		<input checked="" type="checkbox"/> N	Set to Run: Odd Even Every Days	
							or Days of the Week: S M T <input checked="" type="checkbox"/> T F S	

			Repairs Proposed (P) or Completed (C)												Comments and Recommendations								
Controller	Plant Type			Pipes		Valves			Broken Heads			Adjustments											
Zone	Head Type (Rotor, Spray, Drip, etc.)	Turf	Shrub	Annual	Mainline Break	Lateral Line Break	Zone Not Responding	Valve Leaking	Zone Not Shutting Down	Turf Spray (4")	Shrub Spray (12")	Fixed Riser	Gear Driven Rotor	Impact Rotor		Cleaned/Replaced Nozzle	Adjust Spray Pattern	Straightened	Capped	Raised/Lowered			
1	<i>R</i>	<i>1</i>	<i>1</i>													<i>1</i>	<i>1</i>				<i>10:00 pm</i>  <i>1st half Island</i> <i>2nd half Island</i>		
2	<i>R</i>	<i>1</i>	<i>1</i>	<i>1</i>									<i>2</i>				<i>1</i>	<i>1</i>					
3																							
4																							
5																							
6																							
7																							
8																							
9																							
10																							
11																							
12																							
13																							
14																							
15																							
16																							
17																							
18																							
19																							
20																							
21																							
22																							
23																							
24																							

Comments

# Irrigation Technical Inspection Report

Irrigation Controller			Point of Connection			Site Name: <i>Coral Stone</i>	
Location: <i>At Mail Box</i>	Location: <i>At Mail Box</i>		Location: <i>At Mail Box</i>		Location: <i>Acroyle Forest</i>		
Type/Size: <i>2" B.</i>	Size: <i>2"</i>		Technician: <i>Roth</i>		Date of Inspection: <i>1.5.18</i>		
Rain Gauge: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Source: <input checked="" type="checkbox"/> Meter <input type="checkbox"/> Well <input type="checkbox"/> Pump		Date of Inspection: <i>1.5.18</i>		Inspection #: <i>of</i> in contract		
Power On: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Backflow: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N		Inspection Start Time: <i>7a</i>		Inspection End Time: <i>4p</i>		
General Information			PRV: <input type="checkbox"/> Y <input checked="" type="checkbox"/> N		Set to Run: <input type="checkbox"/> Odd <input type="checkbox"/> Even <input type="checkbox"/> Every Days		
Valve Type	Master Valve: <input type="checkbox"/> Y <input checked="" type="checkbox"/> N		or Days of the Week: <i>S M T <input checked="" type="checkbox"/> T F S</i>				
Adequate Coverage: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N							

Controller		Plant Type			Repairs Proposed (P) or Completed (C)										Comments and Recommendations						
Zone	Head Type (Rotor, Spray, Drip, etc.)	Turf	Shrub	Annual	Pipes		Valves			Broken Heads			Adjustments								
					Mainline Break	Lateral Line Break	Zone Not Responding	Valve Leaking	Zone Not Shutting Down	Turf Spray (4")	Shrub Spray (12")	Fixed Riser	Gear Driven Rotor	Impact Rotor	Cleaned/Replaced Nozzle	Adjust Spray Pattern	Straightened	Capped	Raised/Lowered		
1	S	1	1																		<i>10:00pm</i>  At Mail Box 9450-9474 9480-9498 8691-8691 8649-8631 8007-8589 8583-8529 9380-9402 9408-9432 9432-9474 9480-8631 8607-8589 8583-8559 9380-9432
2	S	1	1																		
3	S	1	1																		
4	S	1	1							2					2						
5	S	1	1																		
6	S	1	1																		
7	S	1	1																		
8	S	1	1							1					1						
9	S	1	1																		
10	R	1	1							X											
11	R	1	1							X											
12	R	1	1																		
13	R	1	1																		
14	R	1	1																		
15																					
16																					
17																					
18																					
19																					
20																					
21																					
22																					
23																					
24																					

Comments

# Irrigation Technical Inspection Report

Irrigation Controller			Point of Connection			Site Name: <i>Corner Stone</i>	
Location	<i>Entry Sign</i>		Location	<i>Grand Falls</i>		Location: <i>Arroyo Forest</i>	
Type/Size	<i>R.D.</i>		Size	<i>1 1/2"</i>		Technician: <i>Patrick</i>	
Rain Gauge	<input checked="" type="checkbox"/>	N	Source	<input checked="" type="checkbox"/> Meter	Well	Pump	Date of Inspection: <i>2-5-18</i>
Power On	<input checked="" type="checkbox"/>	N				Inspection #: of in contract	
General Information			Backflow	<input checked="" type="checkbox"/>	N	Inspection Start Time: <i>2:00</i>	
Valve Type			PRV	Y	<input checked="" type="checkbox"/> N	Inspection End Time: <i>4:00</i>	
Adequate Coverage	<input checked="" type="checkbox"/>	N	Master Valve	Y	<input checked="" type="checkbox"/> N	Set to Run: Odd Even Every Days	
						or Days of the Week: S M T <input checked="" type="checkbox"/> T F S	

		Repairs Proposed (P) or Completed (C)															Comments and Recommendations					
Controller	Plant Type	Pipes		Valves			Broken Heads					Adjustments										
Zone	Head Type (Rotor, Spray, Drip, etc.)	Turf	Shrub	Annual	Mainline Break	Lateral Line Break	Zone Not Responding	Valve Leaking	Zone Not Shutting Down	Turf Spray (4")	Shrub Spray (12")	Fixed Riser	Gear Driven Rotor	Impact Rotor	Cleaned/Replaced Nozzle	Adjust Spray Pattern		Straightened	Capped	Raised/Lowered		
1	<i>B</i>	-	-																		<i>10:00 AM</i>	
2	<i>S</i>	-	-																		<i>Entry Sign</i>	
3	<i>R</i>	-	-																		<i>Back near Village Plaza</i>	
4	<i>R</i>	-	-																		<i>Grand Falls east</i>	
5	<i>R</i>	-	-																		<i>" " Roadside</i>	
6	<i>R</i>	-	-										<i>2</i>								<i>" " "</i>	
7																						
8																						
9																						
10																						
11																						
12																						
13																						
14																						
15																						
16																						
17																						
18																						
19																						
20																						
21																						
22																						
23																						
24																						

Comments

---



---



---

# Irrigation Technical Inspection Report

Irrigation Controller			Point of Connection			Site Name:	
Location	8637		Location	8647		Corner Stone South	
Type/Size	L.B.		Size	2"		Location: Apple Forest	
Rain Gauge	<input checked="" type="checkbox"/>	N	Source	Meter	Well	Technician:	Pattick
Power On	<input checked="" type="checkbox"/>	N				Date of Inspection:	1.5.18
General Information			Backflow	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Inspection # :	of in contract
Valve Type			PRV	Y	<input checked="" type="checkbox"/>	Inspection Start Time:	7a
Adequate Coverage	<input checked="" type="checkbox"/>	N	Master Valve	Y	<input checked="" type="checkbox"/>	Inspection End Time:	4p
						Set to Run:	Odd Even Every Days
						or Days of the Week:	S M T <input checked="" type="checkbox"/> T F S

		Repairs Proposed (P) or Completed (C)													Comments and Recommendations						
Controller	Plant Type	Pipes		Valves			Broken Heads			Adjustments											
Zone	Head Type (Rotor, Spray, Drip, etc.)	Turf	Shrub	Annual	Mainline Break	Lateral Line Break	Zone Not Responding	Valve Leaking	Zone Not Shutting Down	Turf Spray (4")	Shrub Spray (12")	Fixed Riser	Gear Driven Rotor	Impact Rotor		Cleaned/Replaced Nozzle	Adjust Spray Pattern	Straightened	Capped	Raised/Lowered	
1	S	-	-																		10:00pm
2	S	-	-																		8601-8619
3	S	-	-																		8623-8637
4	S	-	-																		8641-8657
5	S	-	-																		8661-8677
6	R	-	-																		Front Lake Btw. S.W.
7	R	-	-																		8601-8609
8	R	-	-																		8613-8629
9	R	-	-																		8631-8647
10	R	-	-																		8649-8665
11	R	-	-																		8669-8677
12	R	-	-																		Front Side Lake
13																					Backside Lake
14																					
15																					
16																					
17																					
18																					
19																					
20																					
21																					
22																					
23																					
24																					

Comments

# Irrigation Technical Inspection Report

Irrigation Controller			Point of Connection			Site Name:	
Location	8719		Location	8606		Corner Stone	
Type/Size	R.D.		Size	2"		Location: Argyle forest	
Rain Gauge	(Y)	N	Source	Meter	Well	Technician: PATRICK	
Power On	(Y)	N				Date of Inspection: 2.5.18	
General Information			Backflow	(Y)	N	Inspection #: of in contract	
Valve Type			PRV	Y	(N)	Inspection Start Time: 7a	
Adequate Coverage	(B)	N	Master Valve	Y	(N)	Inspection End Time: 4p	
						Set to Run: Odd Even 1 Every Days	
						or Days of the Week: S M T (X) T F S	

Controller		Plant Type			Repairs Proposed (P) or Completed (C)										Comments and Recommendations						
Zone	Head Type (Rotor, Spray, Drip, etc.)	Turf	Shrub	Annual	Pipes		Valves			Broken Heads			Adjustments								
					Mainline Break	Lateral Line Break	Zone Not Responding	Valve Leaking	Zone Not Shutting Down	Turf Spray (4")	Shrub Spray (12")	Fixed Riser	Gear Driven Rotor	Impact Rotor	Cleaned/Replaced Nozzle	Adjust Spray Pattern	Straightened	Capped	Raised/Lowered		
1	(S)	1	-													1	1				8725-8726
2	(S)	1	-													1	1				8720-8762
3	(S)	1	-													1	1				8096-8678
4	(S)	1	-													1	1				8672-8654
5	(S)	1	1													1	1				8048-8630
6	(S)	1	1													1	1				8664-8009
7	(S)	1	1													1	1				8590-8572
8	(S)	1	1													1	1				8560-
9																					
10																					
11																					
12																					
13																					
14																					
15																					
16																					
17																					
18																					
19																					
20																					
21																					
22																					
23																					
24																					

10:00 pm

Comments